

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401257623
Date Received:
04/12/2017

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Lorne C Prescott 970 812 5311 cogccnotifications@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680101634
Inspection Date: 04/06/2017 FIR Submit Date: 04/11/2017 FIR Status:

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC Company Number: 10433
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449070

Location Name: Gunderson Number: 20-03 Pad County:
Qtrqr: NENW Sec: 20 Twp: 9S Range: 93W Meridian: 6
Latitude: 39.266756 Longitude: -107.795281

FACILITY - API Number: 05-077-00 Facility ID: 449070

Facility Name: Gunderson Number: 20-03 Pad
Qtrqr: NENW Sec: 20 Twp: 9S Range: 93W Meridian: 6
Latitude: 39.266756 Longitude: -107.795281

CORRECTIVE ACTIONS:

1 CA# 70888

Corrective Action: Install sufficient BMPs in accordance with Good Engineering Practices all along base of Access Rd Fill slope. Refer to photos#6&7. CA Dates given, remain at Dates from Previous Inspection.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 04/12/2017

Operator Comment: As noted by the COGCC inspector, Ditch is considered a BMP according to CDPHE criteria and as such the ditch is being utilized in accordance with Good Engineering Practices. Inspector implies the ditch is "filled", this is inaccurate and is not reflected in any photographs. The ditch is functioning to prevent soil migration to the field. Laramie staff and contractors are monitoring this BMP and maintaining it to assure it is functioning properly. No evidence of soil migration outside the ditch in any photographs provided by Inspector. Construction activity and BMP installation/maintenance is ongoing.

COGCC Decision: **Not Approved**

COGCC Representative: If constructed properly Ditches are an accepted SW BMP but must be constructed specifically for SW Control. An Irrigation ditch is an unacceptable SW control and must be protected from potential SW. Photos were provided that showed blockage of Irrigation ditch (being used as SW BMP). This FIRR has been submitted to report CAs complete, not to dispute CAs. This appears to be a dispute and this form is not for that process.

2  CA# 70889

Corrective Action: Install sufficient BMPs in accordance with Good Engineering Practices. CA Dates given, remain at Dates from Previous Inspection.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 04/12/2017

Operator Comment: Statements and photographs submitted by the inspector do not accurately reflect the adequacy of the BMPs. Existing BMPs have been chosen and installed in accordance with Good Engineering Practices. Laramie staff is aware of the condition of the fill slope and additional BMPs will be implemented as construction activity is completed.

COGCC Decision: **Not Approved**

COGCC Representative: BMPs are not sufficient nor in accordance with Good Engineering Practices. This FIRR has been submitted to report CAs complete, not to dispute CAs. This appears to be a dispute and this form is not for that process.

OPERATOR COMMENT AND SUBMITTAL

Comment: BMPs are sufficient and have been implemented/installed according to Good Engineering Practices.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lorne C Prescott

Signed: _____

Title: Permit & Enviro Complianc

Date: 4/12/2017 3:39:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401257623	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files