

Inspected Facilities

Facility ID: 448268 Type: WELL API Number: 001-09975 Status: DG Insp. Status: DG

Complaint

Comment: Complaint #: 200441289, 200441288
Field Inspector Assigned: C Pesicka
Nature of complaint: Noise and Lighting
If Sound GPS Coordinates of Survey Location: n/a
Inspection Observations:
OGCC was on location at 12:30pm on 4/10/17. All lighting on location was directed downward and inward. None of complainant structures are within 1000' of location. Location is compliant with rule 803.
Location on 4/10/17 is drilling surface hole. Winds were out of west at constant 7-10 mph with gusts of 10-15 mph, therefore sound survey could not be performed.
OGCC will return to location on 4/11/17 to try to run sound survey if conditions permit.

Corrective Action: _____ Date: _____

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: Surface rig; surface hole being drilled

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401255005 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4120003 |
| 684903461 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4120000 |