

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2017

Submitted Date:

04/19/2017

Document Number:

682402017

FIELD INSPECTION FORM

Loc ID 443722 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 26580
Name of Operator: BURLINGTON RESOURCES OIL & GAS LP
Address: PO BOX 4289
City: FARMINGTON State: NM Zip: 87499

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Prasanna, Sonu		Sonu.Prasanna@conocophilli ps.com	All Inspections
Farrell, Larissa		Larissa.L.Farrell@conocophilli ps.com	All Inspections
Strickler, Robert		robert.d.strickler@conocophilli ps.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443723	WELL	XX	10/26/2015	LO	005-07249	Prosper Farms 4-65 2-1 4AH	CI
443724	WELL	XX	10/26/2015	LO	005-07250	Prosper Farms 4-65 2-1 4CH	CI

General Comment:

[This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401252918.](#)

Location Construction

Location ID: 443722 CDP: _____

Comment: [Topsoil salvaged and stored along the western perimeter of location. Topsoil did not appear to be evenly salvaged throughout portions of the location. Some areas only appeared to be salvaged to a depth of 3"-4". An Operator representative was on location and agreed that additional topsoil should be salvaged and would communicate that to the contractor. Per Rule 1002, topsoil shall be stabilized and protected from degradation due to wind and water erosion. Per Rule 1002, BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.](#)

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: [An initial disturbance area along the perimeter of the location of 7.31 acres was mapped on 4/12/2017 using a Trimble Juno 3B handheld device.](#)

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
WADDLES	Yes		

Comments: Erosion BMPs: BMP installed along the north, east, and south of the location in the form of a filtrex wattle.

Other BMPs:

Corrective Action: _____ Date: _____

DITCHES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: BMP has been installed along the western side of the topsoil stockpile.

Other BMPs:

Corrective Action: _____ Date: _____

Comment: At the time of this inspection, the temporary BMP appears suitable during topsoil salvage operations and initial pad construction. More permanent BMPs should be installed upon the completion of pad construction. BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 443723 Type: WELL API Number: 005-07249 Status: XX Insp. Status: CI

Facility ID: 443724 Type: WELL API Number: 005-07250 Status: XX Insp. Status: CI

COGCC Comments

Comment	User	Date
Refer to the attached inspection photos in Document #682402019.	binschusc	04/19/2017
Follow up inspection will be conducted to ensure permanent BMPs have been installed per Rule 1002.	binschusc	04/19/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682402019	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128622