

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2017

Submitted Date:

04/21/2017

Document Number:

680601465

FIELD INSPECTION FORM

Loc ID 333997 Inspector Name: ROY, CATHERINE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre		Sabre.Beebe@bp.com	All Inspections
,		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298141	WELL	PR	09/04/2008	GW	067-09626	FEDERAL LAND BANK C 4	RI
298142	WELL	PR	07/13/2009	GW	067-09627	FEDERAL LAND BANK C 3	RI

General Comment:

This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.

Inspected Facilities

Facility ID: 298141 Type: WELL API Number: 067-09626 Status: PR Insp. Status: RI

Facility ID: 298142 Type: WELL API Number: 067-09627 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by pinion juniper woodland. Revegetation is progressing within the interim reclamation areas.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date _____

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment

Corrective Action

Date _____

Guy line anchors marked? _____

Comment

Corrective Action

Date _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater erosion is occurring within the eastern interim reclamation area. Wattles have failed and channels are forming.

Corrective Action: Stormwater erosion needs to be stabilized within the eastern interim reclamation area. Wattles need to be repaired or replaced as they do not appear sufficient.

Date: 05/31/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601466	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129454