

Inspection Photos

04/24/2017

Operator: H&R Well Services, Inc #36980

Location ID: 389360

Inspection Doc. Number: 682501921

Logan County, CO

SESE Section 10 T10N R53W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: H&R
Location ID: 389360



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: H&R
Location ID: 389360



Photo 2: Photo taken from the northeast end of the location, facing southwest. Photo shows large areas of what appears to have been a salt kill that have not had any reclamation or stabilization performed. Photo also shows pipe debris remains on the location.



Photo 3: Photo taken from the northeast end of the location, facing south. Photo shows large areas of what appears to have been a salt kill that have not had any reclamation or stabilization performed. Photo also shows pipe debris remains on the location.

Inspection Photos
Operator: H&R
Location ID: 389360



Photo 4: Photo taken from the northeast end of the location. Photo shows pipe debris remains on the location. 6 foot measuring stick for reference.



Photo 5: Photo taken from the northeast end of the location. Photo shows areas where the battery facilities likely existed. Photo shows areas where gravel still remain. Inspector was unable to find any evidence that reclamation or CAs from past inspection have been addressed.

Inspection Photos
Operator: H&R
Location ID: 389360



Photo 6: Photo taken from the north end of the location. Photo shows pipe debris remains on the location. 6 foot measuring stick for reference.



Photo 7: Photo taken from the north end of the location. Photo shows stained soil found on location. Inspector was unable to find any evidence that reclamation or CAs from past inspection have been addressed.

Inspection Photos
Operator: H&R
Location ID: 389360



Photo 8: Photo taken from the north end of the location, facing south. Photo shows large areas of what appears to have been a salt kill that have not had any reclamation or stabilization performed.



Photo 9: Photo taken from the north end of the location, facing south. Photo shows large areas of what appears to have been a salt kill that have not had any reclamation or stabilization performed.

Inspection Photos
Operator: H&R
Location ID: 389360



Photo 10: Photo taken from within the salt kill. Photo shows large gully that has formed due to improper site stabilization. 6 foot measuring stick for reference.