



April 17th, 2017

Matt Lepore, Director
Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203

Re: Request for Exception to Rule 317.p

Brnak 1N-64W-10 Pad, Weld County CO

1. Brnak 01N-64W-10-1H- Doc# 401251451 - Sec. 10-T1N-64W NWNW
2. Brnak 01N-64W-10-2H- Doc# 401251452 - Sec. 10-T1N-64W NWNW
3. Brnak 01N-64W-10-3H- Doc# 401251453 - Sec. 10-T1N-64W NWNW
4. Brnak 01N-64W-10-4H- Doc# 401251454 - Sec. 10-T1N-64W NWNW
5. Brnak 01N-64W-10-5H- Doc# 401251456 - Sec. 10-T1N-64W NENW
6. Brnak 01N-64W-10-6H- Doc# 401251457 - Sec. 10-T1N-64W NENW
7. Brnak 01N-64W-10-7H- Doc# 401251458 - Sec. 10-T1N-64W NENW
8. Brnak 01N-64W-10-8H- Doc# 401251460 - Sec. 10-T1N-64W NENW

Dear Director Lepore:

Verdad Resources LLC respectfully requests approval for an Open Hole Logging Exception to Rule 317.p. The above-named wells are requested to be exempt from this requirement due to the proximity of existing well(s) with acceptable petrophysical logs that adequately describes the stratigraphy of the wellbore, adequately verifies surface casing setting depth, and adequately verifies any aquifer coverage. The existing wells listed in the table below have log(s) which meet the offsetting well surface-hole distance and bearing requirements.

Well Name	Number	API Number	Distance From Well(s)	Azimuth (Degrees)	Log Type/Types	Log Type Document Number
Brnak	#21-10	05-123-23292	770	127	Comp. Density, Comp Neutron, Dual Induction	1390949

One of the first wells drilled on the pad will be logged with cased hole Pulsed Neutron Log with Gamma Ray Log from KOP into the surface casing. All wells on the pad will have a cement bond log with gamma-ray run on production casing (or on intermediate casing if production liner is run) into the surface casing. The horizontal portion of every well will be logged with a measured while-drilling gamma-ray log. The Form 5, Completion Report, for each well on the pad will list all logs run in that well and have those logs attached. The Form 5 for each well shall clearly state "No open-hole logs were run" and shall reference the Rule 317.p Exception granted for the well. Should you have any question, please feel to contact me at (720)-394-0933

Sincerely,
Verdad Resources

Kenny Trueax
Regulatory Manager