

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401244140
Date Received:
03/27/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685302238
Inspection Date: 02/22/2017 FIR Submit Date: 02/26/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325581

Location Name: TAICHERT-N33N6W Number: 32SENW County: LA PLATA
Qtrqr: SENW Sec: 32 Twp: 33N Range: 6W Meridian: N
Latitude: 37.063760 Longitude: -107.527189

FACILITY - API Number: 05-067-00 Facility ID: 215036

Facility Name: TAICHERT Number: 32-02 1
Qtrqr: SENW Sec: 32 Twp: 33N Range: 6W Meridian: N
Latitude: 37.063760 Longitude: -107.527189

CORRECTIVE ACTIONS:

1 ☒ CA# 65511

Corrective Action: Repair or install required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for additional details. Corrective action date extended to allow for weather conditions but repair needs to be made as soon as possible to prevent further erosion.

Date: 04/28/2017

Response: CA COMPLETED Date of Completion: 03/27/2017

Operator Comment: BP has installed BMP's on the NW and E sides of location, Cleaned out ditches and fixed berms on all sides of well pad, smoothed out two track road, cleaned up sediment that was on location and reseeded areas that need some stabilization.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Inspector will complete follow-up inspection.

OPERATOR COMMENT AND SUBMITTAL

Comment: BP has installed BMP's on the NW and E sides of location, Cleaned out ditches and fixed berms on all sides of well pad, smoothed out two track road, cleaned up sediment that was on location and reseeded areas that need some stabilization.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 3/27/2017 1:52:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401244140	FIR RESOLUTION SUBMITTED
401244144	Work Completed photos

Total Attach: 2 Files