

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401254121  
Date Received:  
04/09/2017

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685302212  
Inspection Date: 02/17/2017 FIR Submit Date: 02/21/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325523

Location Name: GEARHART-N35N7W Number: 32SWSW County: LA PLATA  
Qtrqr: SWS Sec: 32 Twp: 35N Range: 7W Meridian: N  
Latitude: 37.254126 Longitude: -107.664918

FACILITY - API Number: 05-067- -00 Facility ID: 214941

Facility Name: GEARHART Number: 01-32 1  
Qtrqr: SWS Sec: 32 Twp: 35N Range: 7W Meridian: N  
Latitude: 37.254126 Longitude: -107.664918

CORRECTIVE ACTIONS:

1 ☒ CA# 64893

Corrective Action: Clean up and remediate per Rule 906.a. Date: 03/24/2017

Response: CA COMPLETED Date of Completion: 04/04/2017

Operator Comment: BP has cleaned up and remediated stained soils per rule 906a. See attached closure document with photos

COGCC Decision: Approved

COGCC Representative: Approved by review of operator provided documentation.

2 ☒ CA# 64894

Corrective Action: Repair and Install required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details. Corrective action date extended to allow for winter weather conditions however work should be completed as soon as possible to prevent further sediment migration and erosion.

Date: 04/19/2017

Response: CA COMPLETED

Date of Completion: 04/04/2017

Operator Comment: BP has addressed erosion and storm water issues by performing Erosion Repairs such as Install Rock Run Down, Cleaned up operator debris, Repaired Berm, Spot seeding, and Grading of Well Pad. See attached photos in closure document.

COGCC Decision: Approved

COGCC Representative: Approved by review of operator provided documentation.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: BP has addressed contaminated soils and storm water issues see attached closure document of work completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 4/9/2017 8:22:40 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401254121	FIR RESOLUTION SUBMITTED
401254122	CA closure documentation

Total Attach: 2 Files