

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2017

Submitted Date:

03/30/2017

Document Number:

670201428**FIELD INSPECTION FORM**

Loc ID 322296 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10043Name of Operator: MACKLEY* ARNOLD & DARLEENAddress: 4031 COUNTY RD 320City: RIFLE State: CO Zip: 81650**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210181	WELL	DM	02/24/1961	GW	045-05076	ED T. BERNKLAU 1	DM

General Comment:Orphan well inspection.

Inspected FacilitiesFacility ID: 210181 Type: WELL API Number: 045-05076 Status: DM Insp. Status: DM**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Orphan well. Bond has been claimed. Landowner notified COGCC engineering staff that gas leaking around wellhead appears to have increased. Bradenhead valve is not present. Gas leaking around outside of visible casing string detectable by hand, gas meter, and FLIR camera. Gas meter registered methane but no H2S.

Corrective Action: Plug and abandon.Date: 06/30/2017

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 39.480460 Long: -107.879829Wind: Light Speed: (mph) Direction From: South Weather: Partly Temperature: 65 (F)Assisting Staff Stan Spencer Camera #: ☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
15:00	PM	15:15	PM	Wellhead(s)

Comment: Gas leaking from outside of visible casing string.Corrective Action: Plug and abandon.Date: 06/30/2017