

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2017

Submitted Date:

05/03/2017

Document Number:

685302900

FIELD INSPECTION FORM

Loc ID 325581 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215036	WELL	PR	01/10/1983	GW	067-06641	TAICHERT 32-02 1	PR

General Comment:

[See link at end of report for path to downloadable pictures.](#)

Inspected Facilities

Facility ID: 215036 Type: WELL API Number: 067-06641 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Ditches	Pass			
Compaction	Pass	Gravel	Pass			
Rip Rap	Pass					
Gravel	Pass					
Sediment Traps	Pass					
Ditches	Pass					
Berms	Pass	Compaction	Pass			

Comment: [Corrective action complete.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685302917	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138163
685302918	Repaired access road.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138164
685302919	Rip rap repair.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138165
685302920	New berm at cut slope base.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138166