

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2017

Submitted Date:

04/28/2017

Document Number:

674300891**FIELD INSPECTION FORM**
 Loc ID 397565 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 76104Name of Operator: SAMSON RESOURCES COMPANYAddress: 15 E 5TH ST STE 1000City: TULSA State: OK Zip: 74103**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Lujan, Carlos		carlos.lujan@state.co.us	
Winney, Andrew	307.640.0522	awinney@samson.com	
Perfors, Tracy	(970) 878-3811	tperfors@blm.gov	BLM

**General Comment:**

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: Inspection conducted in response to communication with Tracy Perfors (BLM) regarding a potential landfarm on a location P&A circa 1995. Site appears to be an abandoned landfarm. Soils are spread ~1.5 ft thick on top of deteriorated HDPE liner. Soils have degraded petroleum odor. Spoke with Andrew Winney of Operator (Samson Resources) on 4/28. He stated that Samson never operated a landfarm on this location and believes contaminated soil was hauled to the location by another operator. COGCC database shows no records of spills or remediation from this or nearby wells within ~ ¼ mile radius. Samson collected soil samples exceeding Table 910-1 for TPH. Informed Andrew of COGCC F-19 and F-27 reporting requirements and necessary remediation.

Corrective Action: Samson will submit F-19, haul contaminated soil and liner to landfill, collect confirmation samples and confirm cleanup with a Supplemental F-19. Following spill closure, Samson will complete reclamation per BLM and COGCC 1000 series rules.

Date: 06/30/2017

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401269444	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4134297">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4134297</a>
674300892	landfarm looking SW	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4134294">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4134294</a>
674300893	landfarm looking NE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4134295">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4134295</a>