



photo 1: Facing toward the production equipment.



photo 2: The sound walls remain and have not been repaired.



photo 3: There are noxious weeds beginning to establish next to the equipment.