

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401279447

Date Received:

05/10/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10618

Name of Operator: BISON OIL & GAS LLC

Address: 999 18TH STREET #3370

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Elizabeth Kane

Phone

720-644-6997

Email

ekane@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 673715130

Inspection Date: 03/28/2017

FIR Submit Date: 03/29/2017

FIR Status: _____

Inspected Operator Information:

Company Name: HRM RESOURCES II LLC

Company Number: 10548

Address: 410 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320788

Location Name: HSR-BENNETT-64S63W Number: 20SESE County: ARAPAHOE

Qtrqtr: SESE Sec: 20 Twp: 4S Range: 63W Meridian: 6

Latitude: 39.681461 Longitude: -104.455700

FACILITY - API Number: 05-005- -00 Facility ID: 204926

Facility Name: HSR-BENNETT Number: 16-20

Qtrqtr: SESE Sec: 20 Twp: 4S Range: 63W Meridian: 6

Latitude: 39.681461 Longitude: -104.455700

CORRECTIVE ACTIONS:

1 CA# 70139

Corrective Action: Remove unused boards east of combustor.

Date: 05/12/2017

Response: CA COMPLETED

Date of Completion: 04/06/2017

Operator Comment: Boards were removed from location on 4/6/2017.

COGCC Decision: _____

COGCC
Representative:

2 CA# 70140

Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 05/12/2017

Response: CA COMPLETED

Date of Completion: 05/09/2017

Operator
Comment: Grass was mowed on 4/24/17, and the weeds were sprayed on 5/9/17.

COGCC Decision:

COGCC
Representative:

3 CA# 70141

Corrective Action: Install or repair required BMPs to prevent site degradation and offsite sediment transport per Rule 1002.f.

Date: 05/12/2017

Response: CA COMPLETED

Date of Completion: 05/01/2017

Operator
Comment: Had a discussion with pumper to ensure that he or any vendor providing a service on location will not drive onto location in muddy conditions in order to prevent mud from being tracked out onto the county road. During muddy conditions, pumper will walk into location if access is necessary.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Elizabeth Kane

Signed:

Title: Production Engineer

Date: 5/10/2017 10:32:40 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

Total Attach: 0 Files