

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2017

Submitted Date:

05/11/2017

Document Number:

682402100**FIELD INSPECTION FORM**Loc ID 443722 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Strickler, Robert		robert.d.strickler@conocophilli ps.com	
Farrell, Larissa		Larissa.L.Farrell@conocophilli ps.com	<a href="#">All Inspections</a>
Prasanna, Sonu		Sonu.Prasanna@conocophilli ps.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443723	WELL	XX	10/26/2015	LO	005-07249	Prosper Farms 4-65 2-1 4AH	RI
443724	WELL	XX	10/26/2015	LO	005-07250	Prosper Farms 4-65 2-1 4CH	RI

**General Comment:**[This is a follow up stormwater inspection to FIR Document #682402017.](#)

Inspected Facilities									
Facility ID:	443723	Type:	WELL	API Number:	005-07249	Status:	XX	Insp. Status:	RI
Facility ID:	443724	Type:	WELL	API Number:	005-07250	Status:	XX	Insp. Status:	RI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Culverts	Pass					
Rip Rap	Pass					
Waddles	Pass					Filtrexx wattles need repair/maintenance
Sediment Traps	Pass					Sediment basin
Ditches	Pass					

Comment: It appears the Operator has installed stormwater and erosion control BMPs throughout the location in a manner to minimize erosion, transport of sediment offsite, and site degradation. At the time of this inspection, the location was still under construction. Per conversations with the Operator, ditch and berm BMPs will be directed to the sediment basin upon completion of the location. Per conversations with the Operator, all stockpiles will be seeded, straw mulched and crimped upon completion of the location. BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Please refer to the attached inspection photos in Document #682402101.	binschusc	05/11/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682402101	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4144518">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4144518</a>