

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/10/2017

Submitted Date:

05/11/2017

Document Number:

685100136

FIELD INSPECTION FORM

Loc ID 314567 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 6301 DEAUVILLE BLVD
City: MIDLAND State: TX Zip: 79706

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
haub, Michael	970-697-8385	mhaub@chevron.com	
Fischer, Alex		alex.fischer@state.co.us	
Diane, Peterson	970-675-3842	dlpe@chevron.com	Regulatory Specialist

General Comment:

COGCC environmental staff was on location to inspect the Siphon Ditch #5. While on the Gray 12 location, it was observed that the location berm has eroded on the downhill side. While not required by rule that locations have perimeter berms, Chevron has adopted this as a policy. It is suggested that Chevron inspect the location berms and repair the downhill side to contain any spill fluid on the Gray 12 location.

Location contains wellhead with no other production equipment.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401281099	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4145065