



photo 1: Facing southeast toward the access road which has not been reclaimed.



photo 2: Facing southeast toward the location.



photo 3: Facing northwest at the location. The soils seem compacted in this area and there is inadequate vegetation establishment.



photo 4: The power line remains to the location which must be removed.



photo 5: Tank battery site near Old Victory Highway Lat/Long 39.75884,-104.40135.



photo 6: There is gravel that remains at the tank battery site.



photo 7: The soils seem to be compacted at the tank battery site.



photo 8: Facing southwest toward the tank battery site.