

From: Stripling, Gary [<mailto:Gary.Stripling@blackhillscorp.com>]
Sent: Tuesday, May 30, 2017 4:15 PM
To: Howard, Douglas <Howard4D@kochind.com>
Subject: HSC 4

Sent by an external sender

To whom it may concern,

Daniel Lapp with Koch Ind. met with me @ 11:15am to review risers on the HSC 4 P&A wellsite. We reviewed the risers on location and we both inspected the issues of the concern with the COGCC. The 1st riser on location is a 2" that is connected to our 6" Gathering System to Horseshoe Canyon as an old meter run. There is no place to disconnect since it's tied in directly to the 6" without a valve to isolate below grade.

The 2nd. riser located east of the 1st. is a 1" drip line that is directly tied into the 6" Gathering System as well. These are not flowlines but gathering lines.

Thanks, if you have any question please call me.

Gary Stripling
Superintendent
Black Hills Plateau Production
Office 970-579-2010
Cell ph. 505-486-0314
gary.stripling@blackhillscorp.com



Riser #1: Blackhills operated gathering line riser. Connected to an active 6" gathering line. Formally connected to a meter run (downstream of meter run).



Riser #2: Blackhills operated gathering line drip line connected to 6" active gathering line.



Area overview showing Koch Exploration P&A Horseshoe Canyon #4 well site and Blackhills operated gathering line risers.