

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401275771  
Date Received:  
05/05/2017

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10412  
Name of Operator: AUS-TEX EXPLORATION INC  
Address: 113 N SANTA FE  
City: FLORENCE State: CO Zip: 81226  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

### Additional Operator Contact:

Contact Name	Phone	Email
Axelson, John		john.axelson@state.co.us
Goss, Aaron	303-233-2232/303-495-0327	AGoss@austineexploration.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 682600256  
Inspection Date: 02/01/2017 FIR Submit Date: 02/02/2017 FIR Status:

### Inspected Operator Information:

Company Name: AUS-TEX EXPLORATION INC Company Number: 10412  
Address: 113 N SANTA FE  
City: FLORENCE State: CO Zip: 81226

### LOCATION - Location ID: 439367

Location Name: Pathfinder C-18 Number: #8 County: FREMONT  
Qtrqtr: NWNE Sec: 18 Twp: 20S Range: 69W Meridian: 6  
Latitude: 38.314773 Longitude: -105.150555

### FACILITY - API Number: 05-043-00 Facility ID: 439366

Facility Name: Columbus Number: 1  
Qtrqtr: NWNE Sec: 18 Twp: 20S Range: 69W Meridian: 6  
Latitude: 38.314773 Longitude: -105.150555

### CORRECTIVE ACTIONS:

1 ☒ CA# 63584

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 12/08/2016

Response: CA COMPLETED

Date of Completion: 03/21/2017

Operator Comment: Wattles for stormwater erosion control were ordered up on 1/27/17. Due to austerity measures, manpower was unavailable for immediate response to the required BMPs per Rule 1002.f.

BMPs were completed on 3/21/17, per Rule 1002.f.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: 1) Stormwater BMPs were installed by 3/21/17, per Rule 1002.f.

Inspector noted that previously identified fence repair (close gap in fence) had been done.

Inspector also noted that operator should close pit. Operator is still evaluating any further opportunity in the wellbore and would like to keep the pits open until the final evaluation in 2017.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aaron J Goss

Signed: \_\_\_\_\_

Title: VP/GM Colorado

Date: 5/5/2017 12:31:21 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401275771	FIR RESOLUTION SUBMITTED
401275788	Stormwater BMPs

Total Attach: 2 Files