

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401300750  
Date Received:  
06/05/2017

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10412  
Name of Operator: AUS-TEX EXPLORATION INC  
Address: 113 N SANTA FE  
City: FLORENCE State: CO Zip: 81226  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) Fax: ( )  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Axelsson, John		john.axelson@state.co.us
Goss, Aaron	303-233-2232/303-495-0327	AGoss@austinexploration.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 682600308  
Inspection Date: 06/01/2017 FIR Submit Date: 06/02/2017 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: AUS-TEX EXPLORATION INC Company Number: 10412  
Address: 113 N SANTA FE  
City: FLORENCE State: CO Zip: 81226

### LOCATION - Location ID: 439367

Location Name: Pathfinder C-18 Number: #8 County: FREMONT  
Qtrqtr: NWNE Sec: 18 Twp: 20S Range: 69W Meridian: 6  
Latitude: 38.314773 Longitude: -105.150555

### FACILITY - API Number: 05-043- -00 Facility ID: 439366

Facility Name: Columbus Number: 1  
Qtrqtr: NWNE Sec: 18 Twp: 20S Range: 69W Meridian: 6  
Latitude: 38.314773 Longitude: -105.150555

### CORRECTIVE ACTIONS:

1 ☒ CA# 79338

Corrective Action: Operator shall clean up spill within 48 hours.

Date: 06/04/2017

Response: CA COMPLETED

Date of Completion: 06/05/2017

Operator Comment: Removed all NON E&P Waste containment vessels from location. Contacted Surface Owner and indicated that there had been a spill on his property. Dug trench and removed soiled dirt, plus unsoiled dirt at perimeter of spill area. Filled out Liquid and or Solid Waste Profile Form for Twin Enviro Services (Phantom Landfill). Disposed of 12,710 lbs of soiled and non-soiled perimeter dirt at Phantom Landfill. Backfilled trench with soil.

COGCC Decision: Approved

COGCC Representative: Operator has removed impacted soils and properly disposed of material.

2 ☒ CA# 79339

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 06/30/2017

Response: CA COMPLETED

Date of Completion: 06/06/2017

Operator Comment: Work in progress. Digging 3 to 5 inch trench for wattel placement, secured with a min of 4 to 5 stakes per section. Anticipated completion is 6/6/2017.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Removed all NON E&P Waste containment vessals from location. Contacted Surface Owner and indicated that there had been a spill on his property. Dug trench and removed soiled dirt, plus unsoiled dirt at perimeter of spill area. Filled out Liquid and or Solid Waste Profile Form for Twin Enviro Services (Phantom Landfill). Disposed of 12,710 lbs of soiled and non-soiled perimenter dirt at Phantom Landfill. Backfilled trench with soil.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aaron J Goss

Signed: \_\_\_\_\_

Title: Executive VP

Date: 6/5/2017 4:59:12 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401300750	FIR RESOLUTION SUBMITTED
401300776	SDS SAE 80W 90
401300777	Invoice Twin Enviro Certified Disposal Site
401300778	Twin Enviro Waste Profile Form

Total Attach: 4 Files