

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401276206

Date Received:

05/05/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10412  
Name of Operator: AUS-TEX EXPLORATION INC  
Address: 113 N SANTA FE  
City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Axelson, John		john.axelson@state.co.us
Goss, Aaron	303-233-2232/303-495-0327	AGoss@austinexploration.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682600284  
Inspection Date: 03/16/2017 FIR Submit Date: 03/17/2017 FIR Status:

Inspected Operator Information:

Company Name: AUS-TEX EXPLORATION INC Company Number: 10412  
Address: 113 N SANTA FE  
City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 439554

Location Name: Pathfinder C-18 Number: #4 County: FREMONT  
Qtrqtr: NENE Sec: 18 Twp: 20S Range: 69W Meridian: 6  
Latitude: 38.312172 Longitude: -105.147236

FACILITY - API Number: 05-043-00 Facility ID: 439553

Facility Name: Marco Polo Number: #1  
Qtrqtr: NENE Sec: 18 Twp: 20S Range: 69W Meridian: 6  
Latitude: 38.312172 Longitude: -105.147236

CORRECTIVE ACTIONS:

1  CA# 67081

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details. Date: 12/08/2016

Response: CA COMPLETED Date of Completion: 03/21/2017

Operator Comment: Wattles for stormwater erosion control were ordered up on 1/27/17. Due to austerity measures, manpower was unavailable for immediate response to the required BMPs per Rule 1002.f. BMPs were completed 3/21/17. Erosion wattles were placed for stormwater management per Rule 1002.f.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Inspector noted that stormwater BMPs were not in place. Wattles were ordered and stormwater BMPs were installed 3/21/17.  
Inspector noted that drill pit should be closed, Rule 1003.d. Operator contacted John Axelson, Environmental Supervisor and discussed Operator's desire to delay pit closure until field study could be completed mid-2017, in case there might be additional opportunity to side-track well. If not, efforts would be made to initiate the pit closure.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aaron J Goss

Signed: \_\_\_\_\_

Title: VP/GM Colorado

Date: 5/5/2017 6:31:39 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401276206	FIR RESOLUTION SUBMITTED
401276207	Stormwater BMPs

Total Attach: 2 Files