

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401298164
Date Received:
06/01/2017

FIR RESOLUTION FORM

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Susana Lara-Mesa 303-825-4822 slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 684903662
Inspection Date: 05/02/2017 FIR Submit Date: 05/02/2017 FIR Status:

Inspected Operator Information:

Company Name: K P KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 332911

Location Name: ROLLIE J VINCENT A-62N67W Number: 2SWNE County:
Qtrqtr: SWNE Sec: 2 Twp: 2N Range: 67W Meridian: 6
Latitude: 40.169116 Longitude: -104.855989

FACILITY - API Number: 05-123-00 Facility ID: 332911

Facility Name: ROLLIE J VINCENT A-62N67W Number: 2SWNE
Qtrqtr: SWNE Sec: 2 Twp: 2N Range: 67W Meridian: 6
Latitude: 40.169116 Longitude: -104.855989

CORRECTIVE ACTIIONS:

1 CA# 73755

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 06/02/2017

Response: CA COMPLETED Date of Completion: 05/04/2017

New stained soil at seperator house

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 73756

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 06/02/2017

Response: CA COMPLETED

Date of Completion: 05/04/2017

Operator
Comment: New stained soil at wellhead

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 73757

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 06/02/2017

Response: CA COMPLETED

Date of Completion: 05/04/2017

Operator
Comment: New stained soil at loadouts

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed: _____

Title: VP of Engineering

Date: 6/1/2017 3:15:34 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401298164	FIR RESOLUTION SUBMITTED
401298187	Seperator house
401298189	Wellhead

