

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401298868
Date Received:
06/02/2017

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #210
City: AURORA State: CO Zip: 80016
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Paul Legler	970-768-0950	paulleglerpumping@yahoo.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 678200675
Inspection Date: 04/10/2017 FIR Submit Date: 04/11/2017 FIR Status: _____

Inspected Operator Information:

Company Name: RENEGADE OIL & GAS COMPANY LLC Company Number: 74165
Address: 6155 S MAIN STREET #210
City: AURORA State: CO Zip: 80016

LOCATION - Location ID: 402787

Location Name: HORN-61N54W Number: 2SWNW County: _____
Qtrqr: SWN Sec: 2 Twp: 1N Range: 54W Meridian: 6
Latitude: 40.083475 Longitude: -103.393796

FACILITY - API Number: 05-121- -00 Facility ID: 113233

Facility Name: HORN 2-5 Number: _____
Qtrqr: SWN Sec: 2 Twp: 1N Range: 54W Meridian: 6
Latitude: 40.083475 Longitude: -103.393796

CORRECTIVE ACTIONS:

1 ☒ CA# 70883

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff (rob.young@state.co.us).

Date: 05/11/2017

Response: CA COMPLETED

Date of Completion: 05/25/2017

Oil tank load line rebuilt. Load line valve replaced. Oily soil removed and replaced with clean fill. Wellheads cleaned up. Buckets removed.

Operator
Comment:

COGCC Decision: Approved

COGCC
Representative:

2 ☒ CA# 70884

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 05/11/2017

Response: CA COMPLETED

Date of Completion: 05/25/2017

Operator
Comment: Major pit berm erosion cuts have been filled and repaired. Discussing with contractors how to stabilize pit berm walls to minimize soil transportation off the pit walls.

COGCC Decision: Approved

COGCC
Representative:

3 ☒ CA# 70885

Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 902.b.

Date: 04/12/2017

Response: CA COMPLETED

Date of Completion: 05/25/2017

Operator
Comment: Berms around pit have been rebuilt and releveled. Evaporation fountain electrical supply problem has been diagnosed and repairs are being scheduled. Current pit freeboard is 3 to 4 feet after rebuilding of pit walls.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions complete. Renegade has maintained a good relationship with surface owner and has never had any landowner complaints regarding our operation.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edward Ingve

Signed: _____

Title: Manager/Owner

Date: 6/2/2017 12:20:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401298868	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files