

Status	Receipt	Permit	TWN	tdir	RNG	rdir	SEC	Q160	Q40	UTM_x	UTM_y	Use	Contact/Sample Attempts	Full Name
Eliminated - Wrong Location	3650164A	285730	3 N		65 W		29 SE		NE	527411.3	4449283	Domestic	According to permit documentation, well is actually located in Sec 29 T22S R51W	BELL, JACK
Eliminated - No Access	3652742H	75657-F	3 N		65 W		29 SE		NE	527305.6	4449393.8	Industrial, Irrigation	According to landowner, well feeds pond/ditch along with 2 other wells- no way to sample well individually.	MOSER JOHN R & ELLEN F
Eliminated - No Access	3652742I	75658-F	3 N		65 W		29 SE		NE	527411.4	4449282.9	Industrial, Irrigation	According to landowner, well feeds pond/ditch along with 2 other wells- no way to sample well individually.	MOSER JOHN R & ELLEN F
Eliminated - No Access	3652742K	75660-F	3 N		65 W		29 SE		SE	527409.7	4449035.4	Industrial, Irrigation	According to landowner, well feeds pond/ditch along with 2 other wells- no way to sample well individually.	MOSER JOHN R & ELLEN F
Eliminated - Use	35059	35059-MH	3 N		65 W		29 SE		SE	527214.2	4448996.2	Other (Monitoring Hole)	-	NORTHERN COLORADO WATER CONSERVANCY
Eliminated - Use	25947	25947-MH	3 N		65 W		33 NW		NE	528010.8	4448594.7	Other (Monitoring Hole)	-	MEADOW GOLD DAIRIES
Eliminated - Not funcional	0426939A	52575-F	3 N		65 W		33 NW		NE	528206.4	4448782.2	Irrigation	Attempted a sample on 6/12/17. Well does not have a pump and is no longer operational.	CANNON LAND CO
Eliminated - Use	25720	25720-MH	3 N		65 W		33 NW		SE	528009.6	4448188.7	Other (Monitoring Hole)	-	MEADOW GOLD DAIRIES