

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401278176
Date Received:
05/09/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96705
Name of Operator: WPX ENERGY PRODUCTION LLC
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Deborah Watson 505-333-1880 deborah.watson@wpxenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601494
Inspection Date: 04/11/2017 FIR Submit Date: 05/01/2017 FIR Status:

Inspected Operator Information:

Company Name: WPX ENERGY PRODUCTION LLC Company Number: 96705
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101

LOCATION - Location ID: 326593

Location Name: BONDAD 33-10-N33N10W Number: 11NWNE County: LA PLATA
Qtrqr: NWNE Sec: 11 Twp: 33N Range: 10W Meridian: N
Latitude: 37.121690 Longitude: -107.901720

FACILITY - API Number: 05-067-00 Facility ID: 258550

Facility Name: BONDAD 33-10 Number: 5A
Qtrqr: NWNE Sec: 11 Twp: 33N Range: 10W Meridian: N
Latitude: 37.121690 Longitude: -107.901720

CORRECTIVE ACTIONS:

1 CA# 73066

Corrective Action: This is the second corrective action for stormwater erosion within the project area as corrective actions are not sufficiently addressed. Diversions and roadside ditches need stormwater controls to de-energize stormwater flows and catch sediment. Culvert on the access road needs further stabilization as soil placed on top will only erode back into the drainage. Revegetation is needed where vegetation has been damaged or removed or to stabilize exposed soils. Corrective action date for corrective actions documented in December inspection will remain the same. Stormwater erosion needs to be controlled within the project area by May 15, 2017.

Date: 04/01/2017

Response: CA COMPLETED Date of Completion: 05/04/2017

The Storm water erosion mentioned above and shown in the pictures included in the inspection on the south-

Operator Comment: eastern portion, Western fill slopes and the access road where it crosses the drainage north west of the location were further repaired and disturbed soil was reseeded on 5/4/2017. See attached photographs documenting completed work.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Deborah Watson

Signed: _____

Title: Environmental Specialist

Date: 5/9/2017 11:48:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401278176	FIR RESOLUTION SUBMITTED
401278200	Corrective Action Completed Photos

Total Attach: 2 Files