

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401309694
Date Received:
06/15/2017

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 1801 BROADWAY #1000
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Redmond, Nolan	720-484-2347	Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303044
Inspection Date: 05/09/2017 FIR Submit Date: 05/11/2017 FIR Status: _____

Inspected Operator Information:

Company Name: ELM RIDGE EXPLORATION COMPANY LLC Company Number: 26625
Address: 12225 GREENVILLE AVE STE 950
City: DALLAS State: TX Zip: 75243-9362

LOCATION - Location ID: 311903

Location Name: SEMLER GAS UNIT-N33N8W Number: 16SWSE County: LA PLATA
Qtrqr: SWSE Sec: 16 Twp: 33N Range: 8W Meridian: N
Latitude: 37.099870 Longitude: -107.719290

FACILITY - API Number: 05-067-00 Facility ID: 216303

Facility Name: SEMLER GAS UNIT Number: 1
Qtrqr: SWSE Sec: 16 Twp: 33N Range: 8W Meridian: N
Latitude: 37.099870 Longitude: -107.719290

CORRECTIVE ACTIONS:

1 ☒ CA# 75391

Corrective Action: Clean up and remediate soil to comply with Rule 906.a. Date: 06/11/2017

Response: CA COMPLETED Date of Completion: 06/09/2017

Operator Comment: Clean up stained soil, place in new rod base and install new muffler, removing old ones

COGCC Decision: Approved pending re-inspection

Follow up inspection to be completed.

COGCC
Representative:

2 ☒ CA# 75392

Corrective Action: Remove debris to comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 06/11/2017

Response: CA COMPLETED

Date of Completion: 06/09/2017

Operator
Comment: Removed old flex pipe and debris.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Follow up inspection to be completed.

3 ☒ CA# 75393

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 06/11/2017

Response: CA COMPLETED

Date of Completion: 06/13/2017

Operator
Comment: Installed lube oil tank spill prevention.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Follow up inspection to be completed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed:

Title: Geo/Eng Tech

Date: 6/15/2017 10:17:01 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401309694	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files