

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401314000
Date Received:
06/21/2017

FIR RESOLUTION FORM

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 24320
Name of Operator: DIAMOND OPERATING, INC.
Address: 6666 GUNPARK DR STE #200
City: BOULDER State: CO Zip: 80301
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Dave Peterson 303-494-4420 davep@flatironenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688000014
Inspection Date: 06/13/2017 FIR Submit Date: 06/19/2017 FIR Status:

Inspected Operator Information:

Company Name: DIAMOND OPERATING, INC. Company Number: 24320
Address: 6666 GUNPARK DR STE #200
City: BOULDER State: CO Zip: 80301

LOCATION - Location ID: 316973

Location Name: MARICK STATE-63S52W Number: 3NWSE County: WASHINGTON
Qtrqr: NWSE Sec: 3 Twp: 3S Range: 52W Meridian: 6
Latitude: 39.819153 Longitude: -103.188416

FACILITY - API Number: 05-121-00 Facility ID: 233649

Facility Name: MARICK STATE Number: 1
Qtrqr: NWSE Sec: 3 Twp: 3S Range: 52W Meridian: 6
Latitude: 39.819153 Longitude: -103.188416

CORRECTIVE ACTIONS:

1 CA# 82678

Corrective Action: Remove stained soil and identify and correct the cause of the overflow condition. Provide a FIRR describing the cause of the overflow and the corrective action. Date: 07/14/2017

Response: CA COMPLETED Date of Completion: 06/20/2017

Operator Comment: A mix of rain water (est. 95%) and produced water (est. 5%) was sucked up from the low area adjacent to the water tank. Removal on slightly impacted soil has been scheduled.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Cause of the problem -- we think a siphon break in a 3" siphon line was temporarily blocked. A small amount of fluid from the water tank come out the top of the siphon line and ran down the sides of the line and collected in a low area adjacent to the water tank. The low area was already full of rain water.
Corrective action plan -- all of the water in the low area has been picked up. On Thursday, June 22 a crew will be onsite and will remove any stained soil and replace it with clean fill dirt.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dave Peterson

Signed: _____

Title: President

Date: 6/21/2017 9:03:33 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

401314000	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files