

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401317344  
Date Received:  
06/23/2017

FIR RESOLUTION FORM

CA Summary:  
2 of 2 CAs from the FIR responded to on this Form  
2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611  
Name of Operator: LONGS PEAK RESOURCES LLC  
Address: 2323 S SHEPHERD SUITE 1150  
City: HOUSTON State: TX Zip: 77019  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
David Clarkson dclarkson@vrtxep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682402113  
Inspection Date: 05/15/2017 FIR Submit Date: 05/18/2017 FIR Status:

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC Company Number: 10611  
Address: 2323 S SHEPHERD SUITE 1150  
City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 438066

Location Name: RAILAY Number: 28-3-1CH County: WELD  
Qtrqr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6  
Latitude: 40.985310 Longitude: -104.783590

FACILITY - API Number: 05-123-00 Facility ID: 438065

Facility Name: RAILAY Number: 28-3-1CH  
Qtrqr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6  
Latitude: 40.985310 Longitude: -104.783590

CORRECTIVE ACTIONS:

1 CA# 76735

Corrective Action: Remove or remediate stained soil. Corrective action date of 5/3/17 remains open until resolved. Date: 05/03/2017

Response: CA COMPLETED Date of Completion: 06/15/2017

Operator Comment: Stained oil has been removed and remediated.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of the FIR resolution acknowledges that the Oil and Gas Conservation

COGCC Representative: Commission has received the Notice. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted to evaluate compliance with COGCC standards.

2  CA# 76736

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 06/15/2017

Response: CA COMPLETED

Date of Completion: 06/15/2017

Operator Comment: Required BMP's for weed control per Rule 1002.f. have been implemented.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the Notice. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted to evaluate compliance with COGCC standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: David Clarkson

Signed: \_\_\_\_\_

Title: COO

Date: 6/23/2017 1:09:17 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401317344	FIR RESOLUTION SUBMITTED
401317357	Railay 28-3-1CH

Total Attach: 2 Files