

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401309523
Date Received:
06/15/2017

FIR RESOLUTION FORM

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

3 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10630

Name of Operator: ALTA MESA SERVICES LP

Address: 15021 KATY FREEWAY SUITE 400

City: HOUSTON State: TX Zip: 77094

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

JAMESON MAX

mjameson@altamesa.net

COGCC INSPECTION SUMMARY:

FIR Document Number: 673504439

Inspection Date: 06/12/2017

FIR Submit Date: 06/13/2017

FIR Status: _____

Inspected Operator Information:

Company Name: ALTA MESA SERVICES LP

Company Number: 10630

Address: 15021 KATY FREEWAY SUITE 400

City: HOUSTON State: TX Zip: 77094

LOCATION - Location ID: 429618

Location Name: Freeman Number: 3-24 County: HUERFANO

Qtrqr: NWS Sec: 24 Twp: 27S Range: 69W Meridian: 6

Latitude: 37.684828 Longitude: -105.067631

FACILITY - API Number: 05-055-00 Facility ID: 429619

Facility Name: Freeman Number: 3-24

Qtrqr: NWS Sec: 24 Twp: 27S Range: 69W Meridian: 6

Latitude: 37.684828 Longitude: -105.067631

CORRECTIVE ACTIONS:

1 CA# 81622

Corrective Action: Comply with Rule 603.f. Remove unused equipment.

Date: 06/22/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator
Comment:

1. Interim Reclamation does not seem to apply to Alta Mesa in the current status of the well because Alta Mesa has taken over the operation in 2016, and plans to complete and produce the well. The reclamation will be performed after the completion activities are finished
2. The unused equipment are the components of the temporary land tank that needs to be assembled to contain

the frac water. It will be erected once a minimum volume of water is supplied to hold the plastic liner in place and build the metal outer wall around it.

COGCC Decision: **Not Approved**

COGCC
Representative:

COGCC
Supervisor:

The location has been out of compliance with the interim reclamation rules for approximately 4.5 years, therefore apply for an interim reclamation delay by going through the Interim Reclamation Procedures for Delayed Operations, NTO. Please note this will include securing increased bonding on the location for 3rd party cost to conduct the interim reclamation. Submit the Form 4 for the delayed interim reclamation by the corrective action (CA) date. The CA will continue to stand until a completed request is submitted.

2  CA# 81623

Corrective Action: Comply with Rule 603.f.
Comply with Rule 1003 f. Perform noxious weed control.

Date: 06/22/2017

Response: CA COMPLETED

Date of Completion: 06/22/2017

Operator
Comment:

We are in the process of mechanically removing noxious weeds without using chemicals.

COGCC Decision: **Not Approved**

COGCC
Representative:

COGCC
Supervisor:

No documentation was provided that the CA was completed i.e. photos. If you are in the "process" of completing the CA it is not complete as stated by your response.

3  CA# 81624

Corrective Action: Comply with Rule 603.f. Remove degraded hay bales.

Date: 06/22/2017

Response: CA COMPLETED

Date of Completion: 06/22/2017

Operator
Comment:

The hay bales function as Stormwater control mechanism and noise barrier. The degraded ones will be removed and used as mulch to stabilize the exposed soil in the newly disturbed area

COGCC Decision: **Not Approved**

COGCC
Representative:

COGCC
Supervisor:

CA does not appear to be complete by the operator comment. No documentation has been provided that the CA was conducted by the CA date.

4  CA# 81625

Corrective Action: Perform Interim reclamation and reduce the size of the location as specified in the 2A.

Date: 06/12/2014

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator
Comment:

Interim Reclamation does not seem to apply to Alta Mesa in the current status of the well because Alta Mesa has taken over the operation in 2016, and plans to complete and produce the well. The reclamation will be performed after the completion activities are finished.

COGCC Decision: **Not Approved**

COGCC
Representative:

COGCC
Supervisor:

The location has been out of compliance with the interim reclamation rules for approximately 4.5 years, therefore apply for an interim reclamation delay by going through the Interim Reclamation Procedures for Delayed Operations, NTO. Please note this will include securing increased bonding on the location for 3rd party cost to conduct the interim reclamation. Submit the Form 4 for the delayed interim reclamation by the corrective action (CA) date. The CA will continue to stand until a completed request is submitted.

5  CA# 81626

Corrective Action: Install required BMPs per Rule 1002.f.

Date: 06/27/2017

Response: CA COMPLETED

Date of Completion: 06/22/2017

Operator
Comment:

The comments seem to refer to the secondary access road that comes off the southwest side of the existing pad area. Wattles will be installed along the access road to control the Stormwater. The degraded hay from the northern fence of the pad will be used as mulch to stabilize the disturbed soil.

COGCC Decision: **Not Approved**

COGCC
Representative:

COGCC
Supervisor:

Corrective action not complete per comments.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Jameson

Signed: _____

Title: Regulatory Coordinator

Date: 6/15/2017 9:35:35 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401309523	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files