

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401331901

Date Received:

07/05/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10110  
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC  
Address: 1801 BROADWAY #500  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Leonard, Mike</u>		<u>mike.leonard@state.co.us</u>
.		<u>cogccinspections@gwogco.com</u>
<u>Adamczyk, Megan</u>		<u>megan.adamczyk@state.co.us</u>
<u>Precup, Jim</u>		<u>james.precup@state.co.us</u>
<u>Gomez, Jason</u>		<u>jason.gomez@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 674005425  
Inspection Date: 06/28/2017 FIR Submit Date: 06/28/2017 FIR Status:

Inspected Operator Information:

Company Name: GREAT WESTERN OPERATING COMPANY LLC Company Number: 10110  
Address: 1801 BROADWAY #500  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 440858

Location Name: Simpson FD Pad Number: 15-219HN County: WELD  
Qtrqtr: SENE Sec: 15 Twp: 6N Range: 67W Meridian: 6  
Latitude: 40.488317 Longitude: -104.874178

FACILITY - API Number: 05-123-00 Facility ID: 449252

Facility Name: Simpson FD Number: 16-379HC  
Qtrqtr: SENE Sec: 15 Twp: 6N Range: 67W Meridian: 6  
Latitude: 40.488317 Longitude: -104.874178

CORRECTIVE ACTIONS:

1 CA# 84011

Corrective Action: Comply with noise regulations established in Rule 802 and further restricted in Rule 604.c.(2)A when the location is within a designated setback location. (NOTE: THIS IS COMPLAINT DRIVEN).

Date: 06/30/2017

Response: CA COMPLETED

Date of Completion: 06/30/2017

Operator Comment: GWOG and drilling contractor worked to isolate different equip to try & find low frequency source. Acoustic blankets were installed in front of the shale shaker and around drawworks blower on rig floor. Mobile acoustic walls were placed in front of shaker and on the prod battery near open area (with no sound walls). The mobile walls in front of shaker did not seem to help and may be moved to another location. Anecdotal evidence from south side of pad appear to indicate a reduction in low frequency noise. AG Wassenar was on site 6/29/17 to take readings and will compare those with baseline measurements before rig arrival. GWOG will submit sound survey results once available. GWOG emailed complainant Nate Morrison directly to see if he noticed difference after installation of mitigation equipment, but he has not responded back to date.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Laura Harter

Signed: \_\_\_\_\_

Title: Production Tech

Date: 7/5/2017 10:23:48 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files