

Michael Furtaw

From: Schwarz, Paul <Paul.Schwarz@anadarko.com>
Sent: Tuesday, June 27, 2017 1:42 PM
To: Allison, Rick; 'Roy Rudisill'; 'tswain@weldgov.com'; 'tparko@co.weld.co.us'
Cc: Scranton, Lynna; Schneider, Paul; Dinkel, Mike; Chase, Charles; Hamlin, Phil; Mickelson, Erik; LaRue, Sam; Rowley, Taylor [Arcadis US, Inc.]; Avant, Paul; Gililland, Chad; Johnson, Kaylie [Tasman Geosciences L]; Andy Verbonitz; Brian Sulzberger; Jeremy Espinoza; Michael Furtaw; Rob Rebel; Ryan Kritzberger; Ryan Zernis
Subject: RE: State Reportable Notification

Sorry, it appears I did not include the Section number noted below. The corrected legals are SWSW Sec. 33-T5N-R67W. Sorry for the confusion.

Thanks

Paul Schwarz

HSE Representative
Anadarko Petroleum Corp.
Office: 970-515-1431

From: Schwarz, Paul
Sent: Tuesday, June 27, 2017 12:10 PM
To: Allison, Rick <rick.allison@state.co.us>; 'Roy Rudisill' <rrudisill@co.weld.co.us>; 'tswain@weldgov.com' <tswain@weldgov.com>; 'tparko@co.weld.co.us' <tparko@co.weld.co.us>
Cc: Scranton, Lynna <Lynna.Scranton@anadarko.com>; Schneider, Paul <Paul.Schneider@anadarko.com>; Dinkel, Mike <Mike.Dinkel@anadarko.com>; Chase, Charles <charles.chase@anadarko.com>; Hamlin, Phil <Phil.Hamlin@anadarko.com>; Mickelson, Erik <Erik.Mickelson@anadarko.com>; LaRue, Sam <Sam.LaRue@anadarko.com>; Rowley, Taylor [Arcadis US, Inc.] <Taylor.Rowley@anadarko.com>; Avant, Paul <Paul.Avant@anadarko.com>; Gililland, Chad <Chad.Gililland@anadarko.com>; Johnson, Kaylie [Tasman Geosciences L] <Kaylie.Johnson@anadarko.com>; 'Andy Verbonitz' <averbonitz@ltenv.com>; bsulzberger@ltenv.com; Jeremy Espinoza (jespinoza@ltenv.com) (jespinoza@ltenv.com) <jespinoza@ltenv.com>; Michael Furtaw (mfurtaw@ltenv.com) <mfurtaw@ltenv.com>; Rob Rebel <rrebel@ltenv.com>; Ryan Kritzberger <rkritzberger@ltenv.com>; Ryan Z (rzernis@ltenv.com) <rzernis@ltenv.com>
Subject: State Reportable Notification

Good Afternoon,

We had a State reportable release due to groundwater impacts at the tank battery facility noted below. Upon excavating a surface stain, a dumpline with a corrosion hole was encountered. More information will be provided in a forthcoming COGCC Initial Form 19 Release Report. Please let me know if you have any questions.

Thompson 13-33 Tank Battery
API: 05-123-20681
Legals: SWSW Sec. 33-T5N-R67W

Thanks

Paul Schwarz

HSE Representative

Anadarko Petroleum Corp.
Office: 970-515-1431

[Click here for Anadarko's Electronic Mail Disclaimer](#)