

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 95750  
Name of Operator: WESTERN INTERIOR ENERGY INC  
Address: P O BOX 247  
City: CRESTED BUTTE State: CO Zip: 81224

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Grogg, Cindy	970-349-5885	wiedmo@msn.com
TRUETTNER JIM	970-349-5883	wiewjt@msn.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 673504352  
Inspection Date: 06/01/2017 FIR Submit Date: 06/01/2017 FIR Status:

Inspected Operator Information:

Company Name: WESTERN INTERIOR ENERGY INC Company Number: 95750  
Address: P O BOX 247  
City: CRESTED BUTTE State: CO Zip: 81224

LOCATION - Location ID: 376278

Location Name: HILTON-63S62W Number: 18SWSE County: ADAMS  
Qtrqtr: SWSE Sec: 18 Twp: 3S Range: 62W Meridian: 6  
Latitude: 39.784196 Longitude: -104.365184

FACILITY - API Number: 05-001-00 Facility ID: 202134

Facility Name: HILTON Number: 3-X  
Qtrqtr: SWSE Sec: 18 Twp: 3S Range: 62W Meridian: 6  
Latitude: 39.784196 Longitude: -104.365184

CORRECTIVE ACTIONS:

1 CA# 79093

Corrective Action: All Risers/ Flowlines/ Pipelines must abide by the phase II of the May 2, 2017 Flowline NTO. Respond when corrective action is complete with date completed and photos attached to an FIRR response to CA. Make sure to identify both endpoints of all riser Risers/ Flowlines/ Pipelines .

Date: 06/30/2017

Response: CA COMPLETED

Date of Completion: 07/03/2017

Operator Comment: see new attachment

COGCC Decision: **Not Approved**

COGCC Representative: Rule 1004 requires "All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well."  
The pipe riser was located at the location and must be removed to comply with Rule 1004.

2  CA# 79094

Corrective Action: All Risers/ Flowlines/ Pipelines must abide by the Phase I of the May 2, 2017 Flowline NTO. Respond when corrective action is complete with date completed and photos attached to an FIRR response to CA. Make sure to identify both endpoints of all Risers/ Flowlines/ Pipelines.

Date: 05/31/2017

Response: CA COMPLETED

Date of Completion: 07/03/2017

Operator Comment: see new attachment

COGCC Decision: **Not Approved**

COGCC Representative: Rule 1004 requires "All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well."  
The pipe riser was located at the location and must be removed to comply with Rule 1004.

3  CA# 79095

Corrective Action: Remove the electric utilities from the location. Perform noxious weed control practices.

Date: 06/30/2017

Response: CA COMPLETED

Date of Completion: 07/03/2017

Operator Comment: See attached contract with IREA to remove power line.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Documentation regarding noxious weed control was not included.  
The attached contract does not clearly specify removal of the electric utilities. A separate FIRR #401330868 was submitted which documents removal of the electric utilities.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: New attachment added as addendum to original FIRR submitted on 6/28/17

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cindy Grogg

Signed: \_\_\_\_\_

Title: Office Manager

Date: 7/3/2017 11:13:08 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401330538	FIR RESOLUTION SUBMITTED
401330547	Contract with IREA to remove powerline

Total Attach: 2 Files