



photo 1: Facing southeast toward the tank battery



photo 2: There is stained soil around the tank battery.



photo 2: There is a partially buried barrel which is being used for containment. There appears to be oily waste in the barrel which may be the origin of the stained soils.



photo 2: Facing northwest at the backside of the tank battery. The stained soil extends out along the berm area.



photo 5: Southwest side of the location facing east. The stain soil extends out to this shallow pit area.



photo 6: Facing west toward the well.