

Archuleta Dix 2 Closure Documentation 7-20-2016

Photo upon arrival at location during assessment of situation. Investigation of equipment inside and outside of the cabinet did not reveal any active leaks in equipment. Stained soils slated to be shoveled up into bags provided by BP Environmental advisor and transported to Durango Operations Center where stained soils will be deposited into the Soil Box which is managed by Andy Hawk BP for remediation at IEI in Farmington NM.



Photos of stained areas after crew shoveled up all stained soils into bags to be taken to soil box at Durango Operations Center for remediation at IEI. No manifest available as soil box is for all soils cleaned up which are at a non-reportable amount. As demonstrated in photos below the stained soils were removed from around equipment, bagged for deposit into BP soil box and clean soil was placed into the remediated area. All stained soils have been cleaned up closing out CA in COGCC inspection.



Photo of soils that were shoveled up that are bagged and being transported to the soil box at the BP Durango Operations Center for future remediation at IEI.

