

Inspection Photos
Location Fahk-Garrett #3
API:05-001-06011



well sign



well location weeds on location, staining at wellhead



Inspection Photos
Location Fakh-Garrett #3
API:05-001-06011



Unused equipment around treater



Unused equipment around treater

Inspection Photos
Location Fakh-Garrett #3
API:05-001-06011



Unused equipment, scubber



**2 unmarked risers at meter run GPS N 39.90416 W -
103.77816**



Inspection Photos
Location Fakh-Garrett #3
API:05-001-06011



Tank battery, no capacity sign and weeds need maintained



Staining on backside of tank

Inspection Photos
Location Fakh-Garrett #3
API:05-001-06011



Production equipment

