

FORM
6Rev
12/05

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|-----------------------------------|----|----|----|
| DE | ET | OE | ES |
| Document Number: 401357443 | | | |
| Date Received: | | | |

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

| | |
|--|--------------------------------|
| OGCC Operator Number: 10459 | Contact Name: Kaleb Roush |
| Name of Operator: EXTRACTION OIL & GAS INC | Phone: (720) 354-4580 |
| Address: 370 17TH STREET SUITE 5300 | Fax: |
| City: DENVER State: CO Zip: 80202 | Email: kroush@extractionog.com |
| For "Intent" 24 hour notice required, Name: Gomez, Jason Tel: (970) 573-1277 | |
| COGCC contact: Email: jason.gomez@state.co.us | |

| | |
|--|--|
| API Number 05-123-22873-00 | Well Number: B10 |
| Well Name: SHUPE 5 SPOT | |
| Location: QtrQtr: NENE Section: 20 Township: 5N Range: 65W Meridian: 6 | |
| County: WELD | Federal, Indian or State Lease Number: |
| Field Name: WATTENBERG | Field Number: 90750 |

☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

| | |
|---|-------------------------------|
| Latitude: 40.391450 | Longitude: -104.680970 |
| GPS Data: | |
| Date of Measurement: 10/20/2010 | PDOP Reading: 1.2 |
| GPS Instrument Operator's Name: Dave Berglund | |
| Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems | |
| <input type="checkbox"/> Other | |
| Casing to be pulled: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Estimated Depth: 550 |
| Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If yes, explain details below |
| Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If yes, explain details below |
| Details: | |

Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|------------------|-----------|-----------|----------------|---------------------|------------|
| CODELL | 7362 | 7407 | | | |
| NIOBRARA | 7048 | 7260 | | | |
| Total: 2 zone(s) | | | | | |

Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| SURF | 12+1/4 | 8+5/8 | 24 | 498 | 260 | 498 | 0 | VISU |
| 1ST | 7+7/8 | 4+1/2 | 11.6 | 7,588 | 480 | 7,588 | 3,950 | CBL |

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6990 with 20 sacks cmt on top. CIPB #2: Depth 275 with 2 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 94 sks cmt from 650 ft. to 325 ft. Plug Type: STUB PLUG Plug Tagged: ☒

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 94 sacks half in. half out surface casing from 650 ft. to 625 ft. Plug Tagged: ☒

Set 10 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Casing weights are assumed based on pad norms as they were not documented. Plugs will be tagged to ensure coverage.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Kaleb Roush

Title: Production Engineer Date: _____ Email: kroush@extractionog.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: _____

COA Type

Description

| | |
|--|--|
| | |
|--|--|

Attachment Check List

Att Doc Num

Name

| | |
|-----------|------------------|
| 401357459 | WELLBORE DIAGRAM |
|-----------|------------------|

Total Attach: 1 Files

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|---------------------|
| | | Stamp Upon Approval |

Total: 0 comment(s)