

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401341608
Date Received:
07/13/2017

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Inspections, All		SanJuanCOGCC@bp.com
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303090
Inspection Date: 05/15/2017 FIR Submit Date: 05/22/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333593

Location Name: MOFFETT GAS UNIT B- N33N7W Number: 34SESW County: LA PLATA
Qtrqtr: SESW Sec: 34 Twp: 33N Range: 7W Meridian: N
Latitude: 37.055732 Longitude: -107.598017

FACILITY - API Number: 05-067-00 Facility ID: 215109

Facility Name: MOFFETT B Number: 1A
Qtrqtr: SESW Sec: 34 Twp: 33N Range: 7W Meridian: N
Latitude: 37.055732 Longitude: -107.598017

CORRECTIVE ACTIIONS:

1 CA# 77314

Corrective Action: Install or repair sign to comply with Rule 210.b. Date: 07/22/2017

Response: CA COMPLETED Date of Completion: 06/28/2017

Operator Comment: New sign has been placed on location for well head and tank sign has been repaired see attached photos

COGCC Decision: Approved via an AMI

COGCC Representative: Approved using operator submitted photo documentation.

2 CA# 77315

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 06/22/2017

Response: CA COMPLETED

Date of Completion: 06/26/2027

Operator Comment: Well pad has been graded to repair ruts, berm has been repaired, spot seeding has been performed and BMP's have undergone sediment removal. Erosion repairs have been completed, see attached photos

COGCC Decision: Approved via an AMI

COGCC Representative: Approved using operator submitted photo documentation.

OPERATOR COMMENT AND SUBMITTAL

Comment: Both Corrective Actions have been completed see attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 7/13/2017 4:06:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401341608	FIR RESOLUTION SUBMITTED
401341639	Sign CA addressed
401341645	Erosion / Stormwater repairs addressed

Total Attach: 3 Files