

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401350922

Date Received:

07/24/2017

FIR RESOLUTION FORM

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Hughes, Jim

jimo.hughes@state.co.us

Labowskie, Steve

steve.labowskie@state.co.us

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

970-375-7530

Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303553

Inspection Date: 07/13/2017

FIR Submit Date: 07/17/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 306945

Location Name: ARCHULETA DIX G.U.-M34N6W Number: 9SENE County: LA PLATA

Qtrqr: SENE Sec: 9 Twp: 34N Range: 6W Meridian: N

Latitude: 37.229128 Longitude: -107.527561

FACILITY - API Number: 05-067- -00 Facility ID: 281473

Facility Name: ARCHULETA-DIX Number: 2

Qtrqr: SENE Sec: 9 Twp: 34N Range: 6W Meridian: N

Latitude: 37.229128 Longitude: -107.527561

CORRECTIVE ACTIONS:

1 ☒ CA# 86441

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.

Date: 07/20/2017

Response: CA COMPLETED

Date of Completion: 07/20/2017

Operator Comment: BP Compliance Specialist Sabre Beebe spoke with COGCC EPS on 7/19/2017 regarding the stained soils identified during inspection. Mr. Hughes and Ms. Beebe agreed on the plan of shoveling up all stained soils, transporting them to the BP soil box at the Operations Center where it will be remediated at IEI. It was further agreed that during this time the equipment would be inspected for active leaks and if leaks were found BP would have equipment repaired.

On 7/20/17 BP Contract personnel was dispatched to location where they checked equipment for active leaks and did not find equipment leaking. The contract crew then shoveled up all stained soils around equipment and bagged them for transport to soil box at Durango OC. Photos of before and after clean up are attached for your review. There are no manifest associated with this clean up as the amounts are below the reportable limits and the soils will be placed into the BP soil box for remediation at IEI in Farmington NM. Please Contact Sabre Beebe with BP with any further questions.

COGCC Decision: Approved via an AMI

COGCC Representative: Approved using operator submitted photo documentation.

OPERATOR COMMENT AND SUBMITTAL

Comment: As of 7/20/2017 stained soils have been shoveled up, transported off location to soil box closing this CA. See attached documentation.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 7/24/2017 7:53:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401350922	FIR RESOLUTION SUBMITTED
401350929	Stained soil clean up documentation

Total Attach: 2 Files