

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/18/2017

Submitted Date:

07/25/2017

Document Number:

680601816

**FIELD INSPECTION FORM**

Loc ID 325737 Inspector Name: ROY, CATHERINE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
,		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Beebe, Sabre		Sabre.Beebe@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215316	WELL	PR	02/01/2017	GW	067-06921	HUNTINGTON A 1	RI

**General Comment:**

[This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.](#)

**Inspected Facilities**

Facility ID: 215316 Type: WELL API Number: 067-06921 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by Gamble oak shrubland and ponderosa pine woodland. Revegetation is progressing within the interim reclamation areas, although sparse on cut-slopes.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment Black netting debris was observed on the northern and southern cut-slopes.

Corrective Action Properly install or remove black netting on cut-slopes. Care should be taken when removing, not to damage vegetation on the cut-slope.

Date **08/31/2017**

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_



**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater erosion appears to be controlled on the location at this time. Some rilling is occurring along the western cut-slope. This should be monitored and stormwater controls applied if it worsens.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401353327	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4206968">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4206968</a>
680601817	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4206967">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4206967</a>