

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/04/2017

Submitted Date:

08/04/2017

Document Number:

690300012**FIELD INSPECTION FORM**Loc ID 316218 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 56680Name of Operator: MERRION OIL & GAS CORPAddress: 610 REILLY AVENUECity: FARMINGTON State: NM Zip: 87401**Findings:**1 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Philana	(505) 324-5300	pthompson@merrion.bz	
Lujan, Carlos		carlos.lujan@state.co.us	
Merrion, ryan	(303) 6532231	ryan@merrion.bz	
Granahan, Kyle		kyle.granahan@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

Environmental**Spills/Releases:**Type of Spill: CONDENSATEEstimated Spill Volume: 84

Comment: Followup to Spill#451576. 84 bbl release from tank via subsurface drain line to closed pit. Weather is 90 F and clear. No indications of release on surface. No seeps or odor in dry gulch to the North or at surface of former pit. Trackhoe staged on location but no personnel or activity on site. Per spill report "spill is now contained within the pre-existing pit. A roustabout company was notified to replace the non-freeze valve ASAP and will plug off and disconnect the line running to the closed pit. A plan will be submitted within the next couple days to specify the steps involved to remediate the spill"

Corrective Action: Per COA "Assess nature and extent of soil and/or groundwater contamination with confirmation samples. Documentation must include a figure showing spill area with sample locations plus laboratory results. Assess and remediate to Table 910-1 standards and provide documentation in a either a Supplemental F-19 or F-27. A Form-27 Assessment and Remediation Plan is required if extended remediation is planned. Any onsite remediation such as landfarming must also be approved by surface owner (BLM). Any planned remediation other than an immediate "dig and haul" of contaminated soil to an offsite licensed disposal facility must be preapproved by COGCC. Documentation must include a figure showing spill area with sample locations plus laboratory results."

Date: 09/30/2017Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300013	Looking SE. Former pit was SE of Tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4216912