

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
06/27/2017

Submitted Date:  
08/04/2017

Document Number:  
679100110

**FIELD INSPECTION FORM**

Loc ID 441379 Inspector Name: KUBECZKO, DAVE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LP  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Chris Lopez		christopher_lopez@kindermorgan.com	
Dave Kubeczko		dave.kubeczko@state.co.us	

**General Comment:**

Date of Inspection: 06-27-17  
Type of Inspection: Containment, Stormwater, Drilling  
Location Name: CX 8 Pad; CX-8 Well  
Form 2A # 400758213  
Location ID #: 441379  
API #: 05-083-06722  
Conducted inspection for site stormwater/erosion control and drilling activities on 06-27-17; site control includes warning tape and sign-in; no evidence of leaks or spills at wellhead or on the well pad; stormwater/erosion controls are substantial and include straw wattles around entire well pad, straw wattles around topsoil pile, top soil pile and cut and fill slopes have been hydroseeded, cut and fill slopes have reclaim vegetation occurring, 12" to 24" or more complete perimeter compacted earthen berm with diversion trenches both inside and outside of pad and berm; containment includes additional berming around temporary drilling mud tanks and double liner beneath rig and all working areas; cuttings containment include large metal open ended bins, raised at the open end, with liners beneath the bins; access road dust being controlled with water application; H2S warning signage; wind socks; no odors detected during drilling operations; location should be inspected once well has been drilled and completed, flowline tested, and in production.