

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2017

Submitted Date:

08/07/2017

Document Number:

679100112**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
311916 KUBECZKO, DAVE 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dave Kubeczko		dave.kubeczko@state.co.us	
Nolan Redmon		nredmond@catamountep.com	

**General Comment:**Date of Inspection: 7-27-17Type of Inspection: Wildlife Consultation, Containment, StormwaterLocation Name: IGW N33N8W 6SESW Pad; IGW 124 and IGW 125 wellsLocation ID #: 311916Form 2A# 401317831API #: 05-067-09298 and 05-067-09349

Construction stormwater BMPs for well pad (diversion trenches, straw wattles, and other spill stormwater control equipment) and access road (borrow ditch for sediment control) are in-place and these stormwater controls indicate no evidence of offsite migration of fluids or sediment; existing stormwater controls indicate no offsite migration of fluids or sediment to nearby ditch and wetlands to the north of the well pad; however, based on the recent onsite and inspection (7-27-17) conducted by COGCC, additional stormwater controls will be required for the existing well pad area and the tank containment area of this oil and gas location; some cut and fill slopes have been partially re-vegetated; no evidence of leaks or spills at wellhead; tank has secondary containment - no evidence of leaks or spills; signage for tank and wellhead are adequate; CPW indicated that deer timing should be adhered to if possible; however, this location has a surface owner waiver of all CPW recommended wildlife BMPs.