

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2017

Submitted Date:

08/10/2017

Document Number:

689800143

### FIELD INSPECTION FORM

Loc ID 316782 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10469  
 Name of Operator: ENERGY INVESTMENTS INC  
 Address: PO BOX 17630  
 City: GOLDEN State: CO Zip: 80402

**Findings:**

- 9 Number of Comments  
4 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccenforcement@state.co.us	
Chamberlain, Stephen	303-526-0871	energyinv@msn.com	<a href="#">All Inspections</a>
		dnr_cogcc_Engineering@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273763	WELL	PR	02/27/2005	OW	107-06222	WOLF MOUNTAIN 15-2-7-87	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume			
Crude Oil	WELLHEAD	<= 1 bbl			
Comment:	Stained soil at wellhead. Some of it has been covered by fresh gravel, some staining is fresh and ongoing.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date:	04/14/2017

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date	
Type: Bird Protectors	#			
Comment:				
Corrective Action:		Date:		
Type: Flow Line	#			
Comment:	1 2" steel riser observed at wellhead not marked for abandonment, not locked out tagged out.			
Corrective Action:	"Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan."		Date:	08/21/2017
Type: Pump Jack	# 1			
Comment:				
Corrective Action:		Date:		
Type: Emission Control Device	# 1			

Comment:	Not lit. Well pumping.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	YES		
Comment:	Gas being vented or flared during non-upset condition without prior approval from COGCC. Well pumping and ECD/flare is not lit.		
Corrective Action:	Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.	Date:	08/10/2017

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 273763 Type: WELL API Number: 107-06222 Status: PR Insp. Status: PR

**Producing Well**

Comment: Pumping.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Lube oils stored at wellhead and on pumpjack base with no secondary containment/covering.

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 04/14/2017

Pits:  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Follow up to inspection from 3/3/2017 document number 673404171. No corrective actions have been met. In addition, the well was venting as it pumped while ECD/flare was not lit.	waldrone	08/10/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689800144	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223214">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223214</a>