

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/23/2017

Submitted Date:

08/24/2017

Document Number:

679700596

**FIELD INSPECTION FORM**

Loc ID 159595 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10608  
Name of Operator: BNN WESTERN LLC  
Address: 370 VAN GORDON STREET  
City: LAKEWOOD State: CO Zip: 80228

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Scott Yount		scott.yount@tallgrassenergyllp.com	Tallgrass/BNN

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451846	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI

**General Comment:**

[COGCC Environmental Staff Inspection of Spill ID #451846 reported verbally by Operator on 8/19/2017](#)

**Inspected Facilities**

Facility ID: 451846 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

### Environmental

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)
Oily Soil	Piles	Adequate	
Comment	Impacted soil has been stockpiled on the pad within an earthen berm pending offsite disposal		
Corrective Action			Date: _____

**Spill/Remediation:**

Comment: Release occurred at fiberglass fitting outside on secondary containment area. Release covered eastern and northern portion of pad and ran into stormwater detention area. All liquids had been removed at time of the inspection and fiberglass produced water line had been repaired. Operator indicated additional soil removal would occur in detention pond. There was no evidence the release exited the detention pond. Operator will followup with COGCC to resolve the spill using eForm 19 Supplemental Reports including soil confirmation sample results, and root cause/corrective actions.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

### COGCC Comments

Comment	User	Date
NOTE: The BNN injection plant and tanks are located on BNN Wildhorse 16 SWD Pad (Location ID 159595) and include 2 gunbarrels, 24 produced water ASTs and 2 crude oil ASTs plus the injection plant. The Wildhorse 16-13L injection well is located on the Whiting Wild Horse 16-13H well pad (Location ID 420505).	allisonr	08/24/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700597	Repaired piping at release point	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4237092">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4237092</a>
679700598	Detention pond viewing northeast	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4237093">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4237093</a>
679700599	Detention pond outfall	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4237094">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4237094</a>