

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2017

Submitted Date:

08/29/2017

Document Number:

674901915**FIELD INSPECTION FORM**Loc ID 326151 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215952	WELL	PR	12/15/1990	GW	067-07558	DWIGHT SOSSAMAN A 1	EI

General Comment:

On August 25, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Dwight Sossaman A #1. For the most recent field inspection report of this facility, please refer to document #674600180.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical injection system labeled corrosion inhibitor.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on location sign.

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds present on locaiton.		
Corrective Action:	Comply with Rule 603.f	Date:	09/08/2017

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Stock panels and jersey barriers		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Chain link perimeter fencing.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stock panel fencing around electrical supply equipment.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment: Telemetry.			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Chemical injection system.			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for corrosion inhibitor.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 25, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Dwight Sossaman A #1. For the most recent field inspection report of this facility, please refer to document #674600180. During this inspection it was noted that weeds are growing on the location.	hughesj	08/29/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901916	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4239611