

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401390873
Date Received:
08/30/2017

FIR RESOLUTION FORM

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 95750
Name of Operator: WESTERN INTERIOR ENERGY INC
Address: P O BOX 247
City: CRESTED BUTTE State: CO Zip: 81224
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
TRUETTNER JIM	970-349-5883	wiewjt@msn.com
Grogg, Cindy	970-349-5885	wiedmo@msn.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900107
Inspection Date: 08/08/2017 FIR Submit Date: 08/14/2017 FIR Status:

Inspected Operator Information:

Company Name: WESTERN INTERIOR ENERGY INC Company Number: 95750
Address: P O BOX 247
City: CRESTED BUTTE State: CO Zip: 81224

LOCATION - Location ID: 319953

Location Name: HILTON-63S62W Number: 18SESE County: ADAMS
Qtrqtr: SESE Sec: 18 Twp: 3S Range: 62W Meridian: 6
Latitude: 39.784049 Longitude: -104.360626

FACILITY - API Number: 05-001-00 Facility ID: 201989

Facility Name: HILTON Number: 1
Qtrqtr: SESE Sec: 18 Twp: 3S Range: 62W Meridian: 6
Latitude: 39.784049 Longitude: -104.360626

CORRECTIVE ACTIONS:

1 CA# 91892

Corrective Action: Comply with Rule 1004. Remove the 3 pipes along the county road. Fill in the area of subsidence. Date: 09/15/2017

Response: CA COMPLETED Date of Completion: 08/30/2017

Operator Comment: Regarding the pipe identified as a riser, and the associated depressed area: According to Anadarko, this pipe and buried item is a vent for their gathering system. It is not located within our area of production operations. WIE is not responsible for this facility, nor is it qualified, or authorized to do anything about it. Regarding the electric service: All equipment was removed at the time of abandonment, with the exception of the one pole shown in your photo. This service was left at the request of the land owner who thought he would want

to use it at some point in the future. The power was disconnected when he determined not to use it immediately. The other line on the property are part of the area wide power grid of Tri County Electric Coop, and they wish to retain them in place. WIE is not responsible for these lines, nor is it qualified, or authorized to do anything about them. Regarding the weeds: WIE properly leveled off and seeded any areas disturbed by our operations. We will attempt to control any weeds that have moved back into these areas, but considering the nature of the surrounding pasture, it is probably impossible to eliminate them. WIE will continue to cooperate to resolve these issues, but would like to proceed with the documentation necessary to remove us from responsibility.

COGCC Decision: **Not Approved**

COGCC Representative: The site does not comply with 1004 rules. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within 3 months of plugging a well. The Hilton 1 well was plugged and abandoned on 1/22/2013 and all associated equipment and debris should have been removed by 4/22/2013. The electric utilities are considered equipment for the oil and gas operations and are not used elsewhere. The operator must ensure removal of the electric utility occurs. Revegetation and weed control must be performed per the 1004 rules until a final reclamation inspection has passed.

COGCC Supervisor: The site does not comply with 1004 rules. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within 3 months of plugging a well. The Hilton 1 well was plugged and abandoned on 1/22/2013 and all associated equipment and debris should have been removed by 4/22/2013. The electric utilities are considered equipment for the oil and gas operations and are not used elsewhere. The operator must ensure removal of the electric utility occurs. Revegetation and weed control must be performed per the 1004 rules until a final reclamation inspection has passed.

OPERATOR COMMENT AND SUBMITTAL

Comment: After considerable time and expense researching issues brought up in Field inspections from Zenith Field Area, Western Interior Energy, Inc. (WIE) respectfully disagrees with the assessment of reclamation. The wells and production facilities were properly cleaned up and the surface restored in more than compliant fashion with the rules in place at the time - in conjunction with the desires of the land owner. WIE therefore requests that any violations recorded concerning the restoration of this property be removed, and we move towards releasing this property from the operator's bond.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: W. James Truettner, III

Signed: _____

Title: President

Date: 8/30/2017 9:55:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401390873	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files