

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/30/2017

Submitted Date:

08/30/2017

Document Number:

679902894

FIELD INSPECTION FORM

Loc ID 314195 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 61650
 Name of Operator: MURFIN DRILLING COMPANY INC
 Address: 250 N WATER ST STE 300
 City: WICHITA State: KS Zip: 67202

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Esquivel, James	620-272-4913	j280189@pld.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227921	WELL	PR	06/01/2017	GW	099-06248	SCHNEIDER 1-3	PR

General Comment:

(This area is intentionally left blank for general comments.)

Location

Lease Road:

Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to stairs at tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 227921 Type: WELL API Number: 099-06248 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Erosion on access and leading off of location needs maintenance. Erosion around base of meter shed is causing meter shed to lean.
Install BMP to prevent erosion across location

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT