

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401389590
Date Received:
08/29/2017

FIR RESOLUTION FORM

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5300
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Extraction		COGCCInspections@extractionog.com
Jeff Rickars		jrickard@extractionog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900129
Inspection Date: 08/11/2017 FIR Submit Date: 08/15/2017 FIR Status:

Inspected Operator Information:

Company Name: EXTRACTION OIL & GAS INC Company Number: 10459
Address: 370 17TH STREET SUITE 5300
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320101

Location Name: WARREN-61S65W Number: 2SWSW County: ADAMS
Qtrqr: SWS Sec: 2 Twp: 1S Range: 65W Meridian: 6
W
Latitude: 39.989440 Longitude: -104.637060

FACILITY - API Number: 05-001-00 Facility ID: 202622

Facility Name: WARREN Number: 1-2
Qtrqr: SWS Sec: 2 Twp: 1S Range: 65W Meridian: 6
W
Latitude: 39.989440 Longitude: -104.637060

CORRECTIVE ACTIIONS:

1 CA# 92191

Corrective Action: Comply with Rule 1004. Remove the pipe riser from the tank battery site. Remove the plastic pipe from the location and any other equipment or debris that may be present. Date: 09/15/2017

Response: CA COMPLETED Date of Completion: 08/22/2017

Operator Comment: Extraction has requested for a second time for Anadarko midstream to remove their riser, see attached request. Extraction would like to make note that this is our second request, the first request was sent in April 2017.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Extraction must ensure that the riser and all equipment is removed to comply with Rule 1004. Once the riser is removed an FIRR should be resubmitted to document removal.
A follow up inspection will be performed to evaluate compliance of Rule 1004.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff Rickard

Signed: _____

Title: Regulatory Compliance Coo

Date: 8/29/2017 7:32:35 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401389590	FIR RESOLUTION SUBMITTED
401389592	Riser Removal REquest

Total Attach: 2 Files