

Stormwater Inspection

September 6, 2017

Operator: PDC ENERGY INC - 69175

API: 05-123-11129

Weld County, CO

SESE Section 7 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FRYE-SWANSON-FRYE #1
API: 05-123-11129



Photo 1. Photo taken June 29, 2017 from the northeast location, facing North. Appears stormwater and/or irrigation water run-on is flowing onto location which then travels across the eastern location through the wells. Gully erosion is occurring along the eastern location and off location.



Photo 2. Photo taken September 6, 2017 from the northeast location, facing North. Appears the Operator has built up a berm along the north and northeast location to divert run-on onto location through an eastern ditch.

Inspection Photos
Location Name: FRYE-SWANSON-FRYE #1
API: 05-123-11129



Photo 3. Photo taken on June 29, 2017 from the southern location, facing East. Gully erosion is occurring adjacent to the location from stormwater and/or irrigation water run-on onto location.



Photo 4. Photo taken on September 6, 2017 from the southern location, facing East. Gully erosion repairs have been performed.

Inspection Photos
Location Name: FRYE-SWANSON-FRYE #1
API: 05-123-11129



Photo 5. Photo taken on September 6, 2017 from the northeast location, facing North. Photo illustrates berm that has been built to divert run-on onto location.