

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401395439  
Date Issued:  
09/08/2017

**NOTICE OF ALLEGED VIOLATION - ISSUED**

Per Rule 522, the Director has reasonable cause to believe that a violation of the Act, or of any Commission rule, order, or permit has occurred, the Director will require the operator to remedy the violation and may commence an enforcement action seeking penalties by issuing a Notice of Alleged Violation (NOAV). Per Rule 523, an operator who violates the Act, or a Commission rule, order, or permit may be subject to a penalty imposed by Commission order.

**OPERATOR INFORMATION**

OGCC Operator Number: <u>90615</u>	Contact Name and Telephone:
Name of Operator: <u>TUDEX PETROLEUM INC</u>	Name: <u>Lionel Conn</u>
Address: <u>2121 39TH AVE NE UNIT E</u>	Phone: <u>(403) 250-7225</u> Fax: <u>( )</u>
City: <u>CALGARY</u> State: <u>AL</u> Zip: <u>T2E 6R7</u>	Email: <u>lconn@live.ca</u>

Additional Operator Contacts	Email
Judith Hagan	TUDORCORP@hotmail.ca

**Well Location, or Facility Information (if applicable):**

API Number: 05-001-08163-00 Facility or Location ID: \_\_\_\_\_  
 Name: REINHOLT Number: 12-6  
 QtrQtr: NWNE Sec: 12 Twp: 1S Range: 68W Meridian: 6  
 County: ADAMS

**ALLEGED VIOLATION**

Rule: 210.b  
 Rule Description: Signs & Markers- Wells & Batteries  
 Initial Discovery Date: \_\_\_\_\_ Was this violation self-reported by the operator? No  
 Date of Violation: \_\_\_\_\_ Approximate Time of Violation: \_\_\_\_\_  
 Was this a discrete violation of obvious duration? No

Description of Alleged Violation:

Pursuant to Rule 210.b, within 60 days after the installation of a battery, Tudex Petroleum, Inc. (Operator) shall install a permanent sign at the wellhead. This sign shall provide, among other required information, the name of the Operator, a phone number at which the Operator can be reached at all times, and a phone number for local emergency services (911 where available). During an inspection on June 20, 2017 (Doc. No. 685503105), COGCC Staff observed that the signage on site at the Reinholt 12-6 well, API No. 001-08163 ("Well") did not include emergency contact information. COGCC Staff, in Doc. No. 685503105, required Operator to modify the signage to include emergency contact information as required by July 20, 2017. During follow up inspections on July 26, 2017 (Doc. No. 687400118), COGCC Staff observed that the signage had not been modified to include emergency contact information. Operator is therefore in violation of Rule 210.b.

Abatement or Corrective Action Required to be Performed by Operator: \_\_\_\_\_ Corrective Action Due Date: 07/20/2017

**Proper and timely abatement does not preclude the assessment of penalties and an Order Finding Violation.**

Operator shall install signage at the Well including emergency contact information as required by Rule 210.b.

Rule: 309  
 Rule Description: Operator's Monthly Report of Operations  
 Initial Discovery Date: \_\_\_\_\_ Was this violation self-reported by the operator? No  
 Date of Violation: \_\_\_\_\_ Approximate Time of Violation: \_\_\_\_\_

