

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/07/2017

Submitted Date:

09/11/2017

Document Number:

682402728**FIELD INSPECTION FORM**
 Loc ID 319860 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 74165
 Name of Operator: RENEGADE OIL & GAS COMPANY LLC
 Address: 6155 S MAIN STREET #210
 City: AURORA State: CO Zip: 80016
Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- ☒ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201631	WELL	PR	09/09/1975	GW	001-07034	SMITH 20-4	RI

General Comment:

This is a follow-up stormwater inspection to Field Inspection Report Document #682402601. Where corrective actions from the previous inspection report remain unresolved or completed, corrective action dates remain unchanged.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Appears an unused tank is being stored at location and needs to be removed by November 3, 2017 (90 days from the previous Field Inspection Report Document #682402601).		
Corrective Action:	Comply with Rule 603.f .	Date:	11/03/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Operator has only repaired erosion and has not installed required BMPs per Rule 1002.f. Refer to the attached inspection photo for more details.](#)

Corrective Action: [Install required BMPs in accordance with good engineering practices per Rule 1002.f. Corrective actions from the previous inspection were not resolved; therefore, the corrective action dates on this inspection remain the same from the previous inspection.](#)

Date: 08/15/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682402729	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248216